

EYE PROTECTION STANDARDS

Level 1

Standard Eye Protection

- ANSI Z87 Safety Glasses required at all times. Clear or amber for low light conditions, dark for sunny conditions.
- Prescription eye protection must be ANSI Z87 with side shields or "over the top" glasses will be worn.
- All employees must pass standard "pencil test" ft test for eye wear.



Level 2

Sealed Eye Protection

- Tight fitting sealed goggles (with head strap).
- Hybrid glasses, foam lined with head strap.



Level 3

Double Eye Protection

- Regular clear plastic face shield AND goggles.
- Bionic face shield AND safety glasses.
- Welding hood AND safety glasses.
- Mesh face shield AND goggles.
- Full face respirator.
- 'Monogoggle'



MINIMUM PROTECTION LEVEL Eye Protection Standard Task Descriptions

The following standards are the minimum requirements. It is the Superintendent's responsibility to determine if additional eye protection is needed based on the conditions / environment. Superintendents are responsible to ensure PPE is provided, worn, and identified in the JHA.

1

All work operation not specified in the below eye protection standards. Fit test required for all safety glasses.

2

- All chemical use except for fueling vehicles/equipment and using marking paint.
- Cutting or drilling metal below your chest.
- Anyone within 10' of the placement and/or vibration of concrete.
- Performing work overhead, for any length of time.

Note on Overhead Work: Any work above 45 degrees from eye level must use Level 2.

3

- Cutting or drilling above your chest.
- Using a grinder, needle-gun scaler, pressure washer, power blower, or blow pipe.
- Using a cutting torch - **Shade 5 Minimum.**
- Using a chop saw/demo saw or cut off saw.
- Chipping, bushing, breaking, or grinding
- concrete (power tool or hand tool use).
- Welding
- Using a chain saw, weed wacker, jack hammer, chipping gun, rivet buster.
- Nail Gun and Powder-Actuated Tool Use.

