

# EYE PROTECTION STANDARDS

## Level 1

### Standard Eye Protection

- ANSI Z87 Safety Glasses required at all times. Clear or amber for low light conditions, dark for sunny conditions.
- Prescription eye protection must be ANSI Z87 with side shields or "over the top" glasses will be worn.
- All employees must pass standard "pencil test" fit test for eye wear.



## Level 2

### Sealed Eye Protection

- Tight fitting sealed goggles (with head strap).
- Hybrid glasses, foam lined with head strap.



## Level 3

### Double Eye Protection

- Regular clear plastic face shield AND goggles.
- Bionic face shield AND safety glasses.
- Welding hood AND safety glasses.
- Mesh face shield AND goggles.
- Full face respirator.
- 'Monogoggle'



## MINIMUM PROTECTION LEVEL Eye Protection Standard Task Descriptions

*The following standards are the minimum requirements. It is the Superintendent's responsibility to determine if additional eye protection is needed based on the conditions / environment. Superintendents are responsible to ensure PPE is provided, worn, and identified in the JHA.*

## 1

All work operation not specified in the below eye protection standards. Fit test required for all safety glasses.

- All chemical use except for fueling vehicles/equipment and using marking paint.
- Cutting or drilling metal below your chest.
- Anyone within 10' of the placement and/or vibration of concrete.
- Performing work overhead, for any length of time.

## 2

- Cutting or drilling above your chest.
- Using a grinder, needle-gun scaler, pressure washer, power blower, or blow pipe.
- Using a cutting torch - **Shade 5 Minimum.**
- Using a chop saw/demo saw or cut off saw.
- Chipping, bushing, breaking, or grinding

- concrete (power tool or hand tool use).
- Welding
- Using a chain saw, weed wacker, jack hammer, chipping gun, rivet buster.
- Nail Gun and Powder-Actuated Tool Use.

## 3