

WORKING AT HEIGHTS

Fall Protection

- When using fall protection, you need to have an approved fall pro plan
- If fall protection ever changes, stop and get a new plan
- Any time you're over 4' in Washington (6' federal OSHA Standard), you need fall protection
- Never tie off below your D-ring without the correct approvals
- All anchorage points must be above your D-ring
- Always reference fall clearance distances in the users guide

If you fill out a fall protection work plan correctly you will check all these boxes!

Dropped Objects

- Any time you are in fall pro, per the standards above, you have the risk of dropping objects
- Tie off all tools in use when you are over the elevation standards noted above
- Always set up red rope when risk of dropping tools
- All elevated work platforms should have no gaps
- Dropped object netting is to be installed on all elevated work / access platforms