

WESTERN CANADA DISTRICT BEST PRACTICE PERSONAL PROTECTIVE EQUIPMENT VISUAL REFERENCE GUIDE

***FOR ALL REQUIRED PPE, FOLLOW YOUR PROJECT-SPECIFIC GUIDELINES**

**MANDATORY
ON-SITE**



HELMETS
Type II Helmets
(Green new hire sticker
for 30 days)



SAFETY VEST
Class 2 Safety Vest



SAFETY GLASSES
Proper fitting safety glasses



WORK GLOVES
Minimum Cut Level 4 gloves



CONSTRUCTION BOOTS
CSA Approved Boots

DRILLS

CORDESS DRILLS	WHEN WORKING 45° ABOVE LINE OF SIGHT	IF ABOVE PEL	
DRILLS	WHEN WORKING 45° ABOVE LINE OF SIGHT	IF ABOVE PEL	
HAMMER DRILLS	WHEN WORKING 45° ABOVE LINE OF SIGHT	IF ABOVE PEL	IF ABOVE PEL
MAG DRILL	WHEN WORKING 45° ABOVE LINE OF SIGHT		

HOT WORK

CUTTING

	SHADE 5 MINIMUM	BEST PRACTICE	IF ABOVE PEL				

HOT WORK

WELDING

		IF ABOVE PEL				

POWDER ACTUATED

NOTE: CERTIFICATION AND SPECIAL TRAINING REQUIRED PRIOR TO USE.

			IF ABOVE PEL	

SAWS

NOTE: MUST HAVE A KICK-BACK BRAKE.

DEMO SAWS	WHEN WORKING 45° ABOVE LINE OF SIGHT		IF ABOVE PEL Both respiratory protective required	IF ABOVE PEL		SPARK RESISTANT CLOTHES	METALLIC PROTECTION OR STEEL TOE BOOTS
ALL CHAIN SAWS	WHEN WORKING 45° ABOVE LINE OF SIGHT		IF ABOVE PEL Both respiratory protective required	IF ABOVE PEL		CHAINSAW CHAPS	METALLIC PROTECTION OR STEEL TOE BOOTS
RECIPROCATING SAWS	WHEN WORKING 45° ABOVE LINE OF SIGHT						
BAND SAWS	WHEN WORKING 45° ABOVE LINE OF SIGHT						
TABLE SAWS							

PNEUMATIC

IMPACT GUNS	WHEN WORKING 45° ABOVE LINE OF SIGHT		
PRESSURE WASHER			
CHIPPING GUNS			IF ABOVE PEL Both respiratory protective required
BREAKERS			IF ABOVE PEL Both respiratory protective required
			IF ABOVE PEL
			ANTI-VIBRATION GLOVES
			AT FOOT LEVEL

GRINDERS

			IF ABOVE PEL	IF ABOVE PEL	

COMPACTORS

	IF ABOVE PEL	ANTI-VIBRATION GLOVES
	IF ABOVE PEL	ANTI-VIBRATION GLOVES
		METALLIC PROTECTION OR STEEL TOE BOOTS

CONCRETE OPERATIONS

			WETTABLE		

MARINE OPERATIONS

	DATRIX TYPE III PERSONAL FLOTATION DEVICE COMPANY PREFERRED PFD AVOID TYPE V
--	---



THE PERFORM AND PROTECT SHOULD BE USED



GOGGLES REQUIRED WHEN WORKING 45° ABOVE LINE OF SIGHT



SILICA DUST HAZARD



REQUIRES MEDICAL EVALUATION, FIT TEST AND TRAINING PRIOR TO USE.

TWA: TIME-WEIGHTED AVERAGE

FOR ADDITIONAL PPE REQUIREMENTS, REFER TO YOUR SAFETY TEAM OR THE SMALL TOOLS CHART