

# WORKING AT HEIGHTS

## Fall Protection

- ☐ When using fall protection, you need to have an approved fall pro plan
- ☐ If fall protection ever changes, stop and get a new plan
- ☐ Any time you're over 4' in Washington (6' federal OSHA Standard), you need fall protection
- ☐ Never tie off below your D-ring without the correct approvals
- ☐ All anchorage points must be above your D-ring
- ☐ Always reference fall clearance distances in the users guide

If you fill out a fall protection work plan correctly you will check all these boxes!

## Dropped Objects

- ☐ Any time you are in fall pro, per the standards above, you have the risk of dropping objects
- ☐ Tie off all tools in use when you are over the elevation standards noted above
- ☐ Always set up red rope when risk of dropping tools
- ☐ All elevated work platforms should have no gaps
- ☐ Dropped object netting is to be installed on all elevated work / access platforms